In The United States Patent And Trademark Office

Vesa Ahvenniemi et al. Applicant:

January 27, 2012 Date:

Date Filed:

May 23, 2006

Docket No.:

METSO-57

App. No.:

10/595978

Art Unit:

2482

Rao

Patent No.:

7,932,922

Issue Date:

April 26, 2011

For:

Method and Arrangement in Tail

Examiner:

Anand Shashikant

Threading of a Web Forming

Machine

Filed by Electronic Filing System

Notice of Printing Error

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Dear Sir:

A review of the above identified Letters Patent has indicated the existence of the following printing error:

Column 7, line 31, "0.02 lux at f₁" should be - - 0.02 lux at f1 - - as indicated in the original filing of the patent application, page 16, line 4 of the Clean Copy of Substitute Specification under 37 C.F.R. 1.125(c).

It is requested that this Notice of Printing Error be placed in the file wrapper of the above-referenced Letters Patent in order to complete the record.

Respectfully Submitted,

Patrick J. G. Stiennon, Reg. No. 34934

Attorney for Applicant Stiennon & Stiennon

P.O. Box 5649

Madison, Wisconsin 53705-5649

(608) 250-4870